




## RÈGLES D'OR / GOLDEN RULES

Chasse aux anomalies / Spot the Anomalies



<b>1</b> : Work too near unsecured excavation	<b>7</b> : Risk of electrocution	<b>13</b> : Bad posture	<b>19</b> : Risk of drowning
<b>2</b> : Falling Object & Uncontrolled Scaffolding	<b>8</b> : Smoking	<b>14</b> : Dangerous storage	<b>20</b> : Working beyond the hand rail
<b>3</b> : Poor barring	<b>9</b> : Use of Mobile in ATEX zone	<b>15</b> : Unsuitable tool	<b>21</b> : Not wearing helmet
<b>4</b> : Work outside collective protection	<b>10</b> : Parking in the wrong direction and in front of the fire hydrant	<b>16</b> : Unsecured co-activity	<b>22</b> : Lack of retention bund
<b>5</b> : Walk or standing under load	<b>11</b> : Walking outside of a secure route	<b>17</b> : Rushing	
<b>6</b> : Using mobile while driving	<b>12</b> : Working from a ladder	<b>18</b> : Confined space risk	